Report of the Month

Lots of metal showed up in this 1994 F150's oil. What's going on?

To learn more about where the elements are coming from, click here.

MAKE/MODEL: Ford 5.8L 351 CID V-8 FUEL TYPE: Gasoline (Unleaded)

OIL TYPE & GRADE: Gasoline Engine Oil

OIL USE INTERVAL: Miles

ADDITIONAL INFO:

This engine looks rough. Universal averages for the 351 CID show typical wear after about 2,800 miles of oil use, and all of the metals here are high in comparison. Lead stands out the most, and unless most of it is leaded fuel blow by, this is a cautionary amount of bearing wear. Iron shows excess steel wear. The oil is contaminated too, with fuel dilution at an elevated 2.5%. Silicon could be from dirt or sealers, and sodium may be from coolant. The TBN's okay at 2.1. The viscosity is fairly thick, reading like a 10W/60. A closer look is warranted before using this V-8.

	MI/HR on Oil			
	MI/HR on Unit	116,000	UNIT / LOCATION	UNIVERSAL
	Sample Date	1/1/2020	AVERAGES	AVERAGES
Z	Make Up Oil Added			
MILLION				
	ALUMINUM	18	12	
≥	CHROMIUM	10	6	
~	IRON	173	114	22
뜺	COPPER	99	61	7
ā	LEAD	750	387	11
	TIN	18	11	
RTS	MOLYBDENUM	33	80	53
Œ	NICKEL	6	4	
PA	MANGANESE	2	2	
	SILVER	0	0	
Z	TITANIUM	1	1	
70	POTASSIUM	10	9	4
Ĕ	BORON	33	35	46
ELEMENTS	SILICON	54	33	13
Σ	SODIUM	152	95	62
Щ	CALCIUM	2023	2130	1832
Ш	MAGNESIUM	227	122	236
	PHOSPHORUS	845	805	806
	ZINC	1085	969	964
	BARIUM	0	0	
			Values	
			Should Be*	
	SUS Viscosity @ 210°	89.2		
(0	cSt Viscosity @ 100°C	17.78		
ES	Flashpoint in °F	325	>375	Bearings are made up of layers of metal. Often the outer
F	Fuel %	2.5	<2.0	layer is lead babbit, with a bronze layer beneath that. In
ш	Antifreeze %	0.0	0.0	these three pictures you can see how the bearings have
ᆽ	Water %	0.0	0.0	worn through the first layer and into the bronze underneath.
PRO	Insolubles %	0.4	<0.6	<u> </u>
₫	TBN	2.1	>1.0	
	TAN			
	ISO Code			

* THIS COLUMN APPLIES ONLY TO THE CURRENT SAMPLE

The owner of this F150 wanted to put this engine into an older vehicle -- it ran smooth and was quiet -- but reconsidered after seeing the analysis. Oil pressure was okay but after pulling a couple of bearing caps, they decided the engine needed to be rebuilt. Although aluminum and chrome are elevated, the cylinder walls and pistons looked okay. But the main and rod bearings had major wear (lead, copper, and tin). Iron is probably largely from the crankshaft.