

This IO-320 has a problem. Can you tell what it is?

To learn more about where the elements are coming from, [click here](#).

UNIT	MAKE/MODEL: Lycoming IO-320-E2A	OIL TYPE & GRADE: Aircraft Engine Oil
	FUEL TYPE: Gasoline (Leaded)	OIL USE INTERVAL: 5 Hours
	ADDITIONAL INFO: Piper PA18-160, Chrome Cyls	

COMMENTS Thanks for discussing this sample with us on the phone. As you know, we're concerned about the amount of chrome this IO-320 is making. To give the engine some credit, chrome did improve nearly 400 ppm compared to the first sample, though the shorter run helped significantly. But at the same time, you only did a partial oil change after the first sample, so a good portion of the chrome could be carryover. We suggest 1. Compression test/borescope of cylinders 2. Looking into why the engine's running hot 3. Another run of 5 hours to see how chrome trends.

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil	5	UNIT / LOCATION AVERAGES	30	UNIVERSAL AVERAGES
	MI/HR on Unit			220	
	Sample Date	11/30/2020		8/4/2020	
	Make Up Oil Added			5 qts	
ALUMINUM	17	27	27	8	
CHROMIUM	219	611	611	5	
IRON	43	129	129	36	
COPPER	3	9	9	7	
LEAD	1516	4275	4275	2303	
TIN	1	3	3	1	
MOLYBDENUM	0	1	1	0	
NICKEL	1	3	3	2	
MANGANESE	1	2	2	0	
SILVER	0	0	0	0	
TITANIUM	0	0	0	0	
POTASSIUM	0	1	1	1	
BORON	1	2	2	1	
SILICON	6	10	10	5	
SODIUM	3	4	4	1	
CALCIUM	5	33	33	17	
MAGNESIUM	1	2	2	1	
PHOSPHORUS	28	104	104	844	
ZINC	2	6	6	4	
BARIUM	0	0	0	0	



The owner knew something was obviously up when he got that first sample. In addition to metal in the oil report, the engine was seeing consistently high oil temps in cruise (210-230°F), and high CHT temps in #1 & #3 cylinders, as well as slightly rough running/vibrations in cruise & climb. Additionally, he reported, the engine felt very underpowered. "My engine is supposed to be rated at 160HP, but we had quite a difficult time getting off the water with two passengers, and one instructor who flew it said it felt like it had about as much power as his 100HP super cub. (His plane however is not on floats.)"

I suspected the high oil temps might be from a poorly designed/located oil cooler, but several mechanics said that's likely not enough to cause the consistent high temps I was getting, especially since we had the issue when flying in colder temperatures. Since I bought the aircraft used and didn't know the complete history on it, and since the engine only had ~225 hours on it in the 20 years since the major overhaul was done, I decided that I'd play it safe and pull all the cylinders after getting your oil analysis results of the extremely high chrome content, twice in a row.

The company who is inspecting and fixing/replacing my cylinders called me yesterday saying the following was wrong with my cylinders: the wrong piston rings were installed for chrome cylinders; heavy wear in every cylinder- scratches/gouges in #1 & #3 which tells him the plane likely sat for over a year in between startups; evidence of blow by in #1 & #3 - those cylinders also had small cracks developing; and several valves installed backwards (intake installed on exhaust side, & vice versa). He said this isn't a huge issue, but shows the laziness or inattention to detail by the mechanic who installed them (aka a warning sign that they did other things wrong, like use the completely wrong piston rings). So I'm having to get 2 new (reman'd) cylinders to replace the ones with cracks. And then he's overhauling everything else."

This O-300 has a problem. Can you tell what it is?

To learn more about where the elements are coming from, [click here](#).

UNIT	MAKE/MODEL: Continental O-300-A	OIL TYPE & GRADE: Phillips XC (A/C) 20W/50
	FUEL TYPE: Gasoline (Leaded)	OIL USE INTERVAL: 31 Hours
	ADDITIONAL INFO: Cessna 172, Mixed Cyl	

CLIENT	The owner says: In reference to the oil analysis surprise of a week and a half ago and the loaded oil filter media, we found the source of the aluminum flakes - worn piston pin plugs. This single plug was from cylinder # 4 and two more were worn on cylinder # 2. Also, we think the (front) thrust bearing is worn beyond limits, allowing the crankshaft to move too much. Looks like a major overhaul is coming.
--------	--

COMMENTS	Thanks for noting the stuck exhaust valve. Aluminum is really high - high enough to show a problem. If temps got high in the cylinder with the stuck exhaust valve, aluminum could be the result. We are also seeing copper, which in this engine is often from piston pin plugs, connecting rod piston pin bushings, or wrist pin problems. With iron, copper can be from the starter adaptor. Maybe all this will improve now that you've freed the valve, but check for problems anyway. Borescope the cylinders and check compressions. Watch for metal.
----------	--

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil	31	UNIT / LOCATION AVERAGES	38	23	21	UNIVERSAL AVERAGES
	MI/HR on Unit	1,079		1,048	1,011	972	
	Sample Date	1/17/2021		5/28/2020	10/2/2019	3/31/2019	
	Make Up Oil Added	2 qts		4 qts	1.5 qts	1 qt	
ALUMINUM	140	45	10	7	23	8	
CHROMIUM	5	5	3	3	10	4	
IRON	31	45	19	21	108	35	
COPPER	25	14	10	10	10	9	
LEAD	912	1658	1374	1380	2965	2146	
TIN	1	2	2	1	2	1	
MOLYBDENUM	0	1	0	0	2	1	
NICKEL	1	1	1			2	
MANGANESE	1	1	0			1	
SILVER	0	0	0			0	
TITANIUM	0	0	0			0	
POTASSIUM	0	0	0			1	
BORON	0	1	2			1	
SILICON	8	15	10			7	
SODIUM	3	3	3			1	
CALCIUM	53	74	62			18	
MAGNESIUM	28	20	26			10	
PHOSPHORUS	87	241	99			443	
ZINC	27	20	30			5	
BARIUM	0	0	0	0	0	0	



Values Should Be*

PROPERTIES	SUS Viscosity @ 210°F	93.6	86-105	85.8	88.8	84.3
	cSt Viscosity @ 100°C	18.84	17.0-21.8	16.97	17.70	16.59
	Flashpoint in °F	410	>430	480	475	445
	Fuel %	1.0	<1.0	<0.5	<0.5	<0.5
	Antifreeze %	-		-	-	-
	Water %	0.0	0.0	0.0	0.0	0.0
	Insolubles %	0.3	<0.6	0.2	0.3	0.5
	TBN					
	TAN					
	ISO Code					

* THIS COLUMN APPLIES ONLY TO THE CURRENT SAMPLE

416 E. PETTIT AVE. FORT WAYNE, IN 46806 (260) 744-2380 www.blackstone-labs.com