


This 1995 Land Cruiser has a problem. What is it?
 To learn where the elements are coming from, [click here](#) and scroll down.

UNIT	MAKE/MODEL: Toyota 4.5L 6-cyl (1FZ-FE)	OIL TYPE & GRADE: Gasoline Engine Oil
	FUEL TYPE: Gasoline (Unleaded)	OIL USE INTERVAL: 1,500 Miles
	ADDITIONAL INFO:	

COMMENTS G.: There's ambiguity due to all the oil that's been added. Sodium can come from coolant, but we're doubtful that's the source since potassium (also in coolant) is low. Instead, sodium is likely from additive in one of the oils you used. Again though, we can't be 100% sure since the fresh oil could be masking contamination. One thing that isn't hidden is the high amount of wear. Iron is most out of line, coming from steel parts like the cylinders, crank, cam, and lifters. Hopefully that's just an artifact of the neglect and improvement will follow now that the engine is in better hands.

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil	1,500	UNIT / LOCATION AVERAGES			UNIVERSAL AVERAGES
	MI/HR on Unit	195,400				
	Sample Date	9/9/2020				
	Make Up Oil Added	7.5 qts				
ALUMINIUM	31	2			2	
CHROMIUM	1	0			0	
IRON	441	5			6	
COPPER	8	1			2	
LEAD	13	5	#6 cylinder wall showing corrosion highlighted by mild phosphoric foaming.		2	
TIN	2	0		#6 cylinder wall with vertical crack and horizontal corrosion line.	0	
MOLYBDENUM	44	114			65	
NICKEL	1	0			0	
MANGANESE	2	0			1	
SILVER	0	0			0	
TITANIUM	4	0			1	
POTASSIUM	0	2			4	
BORON	62	112			63	
SILICON	19	21			12	
SODIUM	81	20			34	
CALCIUM	1634	1959			1847	
MAGNESIUM	242	281			300	
PHOSPHORUS	1438	788			798	
ZINC	1201	938			943	
BARIUM	0	0	Crack highlighted with marker	Oil cooler full of flaking block sealer.	0	

The owner writes: This engine started to overheat just 1500 miles after I bought it. I eventually got around to pulling the head, assuming I might have a leaking head gasket, and got a surprise. Cylinders #1-5 were in very good shape, smooth walls. Then I got to #6 and saw some staining. Closer inspection showed a *horizontal* line of corrosion and pitting, which indicates water had been sitting in that cylinder at some time in the past, before I purchased this vehicle. I also found, with my finger, a slight irregular *vertical* line, crack, or ridge on the rear wall of that cylinder going into the water jacket. To the eye it appeared just as a stain, but the finger swipe told the story.

So at some point before I got this vehicle the engine likely either hydrolocked and/or overheated and the cylinder wall cracked. Then the previous owner, undisclosed at the time of sale, had dumped in a few bottles of block sealer, then sold the vehicle to me. Also, when I took the cooling system apart, I found block sealer coating the inside of all components, everything coated in that sodium silicate stuff. So the previous owner knew he had a problem and dumped in the sealer, then sold the vehicle.

The cause of the elevated iron and couple other metals was likely from corrosion and a crack in a cylinder wall, and maybe some other minor damage causing other metals to go up a bit. The slightly elevated sodium could be explained by the sodium silicate block sealer added by the previous owner. Now I'm trying to find another block, or maybe sleeve the bad cylinder, and rebuild this block. The photos show the horizontal line of corrosion in the cylinder wall (the whitish foam is weak phosphoric acid I put there to highlight the rust and damage). Another photo was with a marker trying to outline the crack. The photo of the side of the block is where an oil cooler plate would be. That plate is removed so you're looking where the oil cooler normally would sit bathed in coolant. In that one you can see the old block sealer flaking off the surfaces of the water jacket that the previous owner had dumped in the cooling system to try to seal the crack in the cylinder wall.

This 2016 Subaru BRZ has a problem. What is it?
To learn where the elements are coming from,
[click here](#) and scroll down.

UNIT	MAKE/MODEL: Subaru 2.0L (FA20/4UGSE) 4-cyl	OIL TYPE & GRADE: Motul 300V 0W/20
	FUEL TYPE: Gasoline (Unleaded)	OIL USE INTERVAL: 250 Miles
	ADDITIONAL INFO:	

COMMENTS TIMOTHY: There's a lot of metal and silicon present, especially for just 250 miles. Race engines do tend to wear more than their street-only counterparts, but we're not sure that's the only reason why metals are so much higher than universal averages (based on ~5K miles). Parts like pistons/bearings (aluminum), steel shafts and cylinder liners (iron), and brass/bronze bushings (copper) might not be wearing well. Silicon might be partly to blame if it shows dirt, so check air filtration. Recent repairs could be another more harmless explanation. A trace of fuel is usually fine.

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil	250	UNIT / LOCATION AVERAGES	UNIVERSAL AVERAGES
	MI/HR on Unit	30,275		
	Sample Date	4/10/2021		
	Make Up Oil Added			
	ALUMINUM	25	2	3
	CHROMIUM	2	0	0
	IRON	57	9	10
	COPPER	7	2	3
	LEAD	0	0	0
	TIN	2	0	0
	MOLYBDENUM	669	373	162
	NICKEL	0	0	0
	MANGANESE	2	0	1
	SILVER	0	0	0
	TITANIUM	0	16	3
	POTASSIUM	0	1	1
	BORON	20	55	88
	SILICON	87	28	25
	SODIUM	6	5	29
	CALCIUM	2269	1822	1756
	MAGNESIUM	16	440	331
	PHOSPHORUS	781	864	709
	ZINC	859	1024	801
	BARIUM	0	0	0



A fuzzy oil plug is never a happy find.

Values Should Be*

PROPERTIES	Value	Should Be*
SUS Viscosity @ 210°F	51.5	46-57
cSt Viscosity @ 100°C	7.74	6.0-9.7
Flashpoint in °F	385	>385
Fuel %	TR	<2.0
Antifreeze %	0.0	0.0
Water %	0.0	<0.1
Insolubles %	0.2	<0.6
TBN		
TAN		
ISO Code		

The owner writes: About 120 stage miles (so a good chunk of them with the engine at redline) after this report, the engine blew up. You'd correctly called out the high metal content, and a spun bearing on cylinder four finally came apart completely. Attached is a photo of the oil plug. We debated sending what drained out of the pan in for analysis, but decided that we weren't really hunting for trace amounts at that point.