

COMMENTS

Report of the Month

This 2000 Expedition has a problem. What is it? To learn where the elements are coming from, <u>click here</u> and scroll down.

MAKE/MODEL: Ford 4.6L V-8 FUEL TYPE: Gasoline (Unleaded) ADDITIONAL INFO: OIL TYPE & GRADE:Motorcraft Semi-Synthetic 5W/20OIL USE INTERVAL:6,828 Miles

JIM: There's a lot of aluminum in this sample (4.6L V-8 averages are based on a ~5,300-mile run). Excess aluminum in these engines can be from a timing chain tensioner problem, and that may be the case for yours. We're not sure if that would be of any relation to the puff of smoke you see every now and then, but this level of aluminum is cautionary so we suggest you have the engine inspected as soon as possible before a potential failure occurs. Note copper (brass/bronze) and silicon (usually from either sealer/lube or dirt) are also elevated. Resample in 3K miles if all is well.

	MI/HR on Oil MI/HR on Unit Sample Date	6,828 232,669 4/5/2021	UNIT / LOCATION AVERAGES	4,784 92,012 2/10/2005	Charles Alles		UNIVERSAL AVERAGES
-	Make Up Oil Added	3 qts		0.5 qt		- A CARLER AND A	
Z	ALUMINUM	386	4	4		10	4
Ĭ	CHROMIUM	1	1	1			1
	IRON	26	15	15			15
2	COPPER	17	12	12			4
Ш Ш	LEAD	1	0	0	SUL LAND		2
ם	TIN	0	0	0			1
S	MOLYBDENUM	23	5	5			67
Ř	NICKEL	1	1	1	The left side of the timing		1
à	MANGANESE	1	0	0			2
z	SILVER	0	0	0	chain is not riding on the	The timing chair	ר <u>0</u>
~	TITANIUM	2	0	0	guide, it's down <i>in</i> the guide.	tensioner is clea	arly <u>2</u>
É	POTASSIUM	0	0	0		worn on one sid	e. 2
ш	BORON	82	0	0			58
2	SILICON	53	7	7			15
	SODIUM	8	4	4	Left: N	Metal shavings	40
	CALCIUM	1543	1761	1761	on the	ne underside of	1917
	MAGNESIUM	787	49	49	the gi	uide. No bueno	237
	PHOSPHORUS	820	772	772			710
	ZINC	956	974	974			828
	BARIUM	0	0	0			1

The owner writes: Over the winter my low oil pressure light stayed on after a cold start for about 10 seconds - this was really the reason I decided to send in an oil sample. Then again in April on a return trip home, my low oil pressure light came on twice for about 3-4 seconds each time. At this point I had already received your report and knew I had to do something. With 233K on the clock, my motor was stone quiet, ran great, and from what I had been reading, I really didn't think my tensioners/chains were the problem.

Anyway, reluctantly I started the process of tearing it down, knowing I'd be fighting 21 years of living in the rust belt, in search of the problem. Took me about 10 hrs to get the oil pan off thanks to all the pan bolts being rusted and rounded off. Finally got the pan off, very little "slime" in the bottom of the pan but when you touched it, you could tell it was aluminum 'paste'. Oil pickup was clean - I was starting to worry as I was expecting to find a plugged oil pickup. Took me about 12-13 hrs to get both valve covers off as almost half the studs and bolts were a rusted mess (I had to weld nuts to them to get them off).

Once I had the covers off, everything looked intact, but I did notice the tensioner arms looked like maybe the plastic was worn. Had the front cover off in about 30 min and as you can see from the pics, my tensioners still had tension on the chains, but the chains had worn through the arms, and actually were starting to wear into the tensioner pistons. The chains looked pretty good (we estimated they had stretched maybe 1/4" total). The guides looked brand new too, and I thought for 233k miles the engine was extremely clean inside. The DS tensioner piston had a slight amount of side to side play in it, and if you squeezed it moderately hard, you could depress it about 1/4".

I'm hoping this was the cause of my intermittent low oil pressure light (either that or my pressure sensor switch is on its way out). I replaced the chains, guides, arms, tensioners and oil pump (for peace of mind). Got it all buttoned up and after priming the oil pump, it started right up. All back together now, and runs great with no leaks! Call me crazy, but I think the engine is even quieter now! Thanks for the great heads up in my oil report, without it I would have kept driving it, as there was no indication anything was wrong.

©COPYRIGHT BLACKSTONE LABORATORIES 2022