

## Report of the Month

## This C-85 engine has a problem. Can you guess what's going on?

To learn where the elements are coming from. click here and scroll down.

MAKE/MODEL: Continental C-85 FUEL TYPE:

Gasoline (Leaded) ADDITIONAL INFO:

Common Wealth SkyRanger

OIL TYPE & GRADE: Aeroshell W100 Plus (AD)

OIL USE INTERVAL: 40 Hours

	MI/HR on Oil	40		40	50	50	20					
	MI/HR on Unit	339	UNIT /	298	220	125	85		UNIVERSAL			
	Sample Date	6/1/2022	LOCATION AVERAGES	5/11/2022	3/23/2022	12/15/2021	10/26/2021		AVERAGES			
	Make Up Oil Added	5 qts		5.50 qts	7 qts	4 qts	3 qts					
LION	ALUMINUM	24	18	16	22	11	9		7			
	CHROMIUM	4	4	3	4	3	5		4			
MIL	IRON	58	60	49	78	54	107		36			
ER M	COPPER	62	51	57	60	26	27		13			
	LEAD	3380	3017	3313	3834	1541	1211		1419			
Ь	TIN	8	7	8	8	3	6		2			
LS	MOLYBDENUM	0	0	0	1	0	0		1			
N PART	NICKEL	1	1	1	2	1	1		1			
	MANGANESE	1	1	1	1	1	1		1			
	SILVER	0	0	0	0	0	0		0			
3	TITANIUM	0	0	0	0	0	0		0			
LIS	POTASSIUM	0	1	0	2	0	0		0			
ENT	BORON	2	2	2	2	1	1		1			
EΜ	SILICON	6	7	6	8	9	7		8			
H	SODIUM	5	4	3	3	3	3		2			
•••	CALCIUM	3	4	3	5	3	3		23			
	MAGNESIUM	1	2	1	4	2	2		5			
	PHOSPHORUS	1124	1132	1067	1154	1183	1030		522			
	ZINC	7	7	6	9	6	8		8			
	BARIUM	0	0	0	0	0	0		0			
	Values											

Should Be\*

SUS Viscosity @ 210°F	99.4	86-105	97.9	98.1	90.7	77.5	
cSt Viscosity @ 100°C	20.21	17.0-21.8	19.86	19.92	18.14	14.90	
Flashpoint in °F	490	>460	435	485	490	445	
Fuel %	<0.5	<1.0	1.3	<0.5	<0.5	8.0	
Antifreeze %	-		-	-	-	-	
Water %	0.0	0.0	0.0	0.0	0.0	0.0	
Insolubles %	0.3	<0.6	0.3	0.3	0.3	0.3	
TBN							
TAN						·	
ISO Code			_				

<sup>\*</sup> THIS COLUMN APPLIES ONLY TO THE CURRENT SAMPLE

This one was tricky. When copper started really going up, Amanda called the owner to talk about the engine. She asked if by any chance the engine has an oil cooler. The owner said he had added one in between the December 2021 and March 2022 samples. Bingo! That was, we thought, the answer. When new, oil coolers will shed copper in the form of oxides. But copper kept going up after that, when it should have improved. We found out later that the engine spun a bearing. Bearing problems are hard to see in analysis, because the lead babbit outer shell is masked by lead from 100LL blow-by.